

1983 **SJT 400** Addendum—1

Selecta Vision® VideoDisc System CED Addendum Service Data

Model SJT 400

RCA Corporation Consumer Electronics

Technical Publications

P.O. Box 1976 Indianapolis Indiana 46206

RCA Inc.

Technical Publications

Town of Mount Royal - Quebec, Canada H4P 1.8

Canada Stock Numbers:

Add prefix 62 to all stock numbers

Purpose of This Addendum: To Update Replacement Parts List. Filing Instructions: File immediately in front of Basic Service Data.

SUMMARY OF ADDITIONS/CHANGES COVERED BY THIS ADDENDUM

Original Service Data Contents Pa	age(s)	Additions/Changes In This Addendum P	Page(s)
Replacement Parts List	thru /6	Replacement Parts List Revisions	2
Voltage Chart	27	Add Note 4 to page 27	1

Note 4 Digital Pulse See Schematic Waveform

BEFORE REPLACING PARTS, READ THE FOLLOWING:

RCA-Approved Substitute Stock Numbers-Before ordering stock numbers in this parts ist, look to an RCA-approved substitute stock number in the current RCA Distributor & Special Products Price Schedule. This will minimize your service time and avoid ordering parts you already have in

See your RCA Distributor for Replacement Parts and Accessories.

Warranty Status of Assemblies and Parts—The warranty status of some assemblies and parts are indicated by one of the following Warranty Status

- Complete assembly not eligible for warranty exchange or replacement.
 Eligible for warranty exchange for new or rebuilt unit.
 Complete assembly eligible for warranty replacement with new or rebuilt.

All parts listed without a Warranty Status Code symbol are eligible for warranty replacement as discrete components.

Warranty replacement of cabinet parts requires prior approval of RCA.

Warranty Status and Specifications of assemblies and parts are subject to change without notice

PRODUCT SAFETY NOTE—Components marked with a (★) have special characteristics important to safety. Before replacing any of these components, read carefully the PRODUCT SAFETY NOTICE in the Basic Service Data. Do not degrade the safety of the set through improper servicing. Although assemblies as a whole may not be marked with a (*i. replacement of RCA assemblies with other assemblies not RCA approved may result in a safety hazard.

Canada Stock Numbers:

Add prefix 62 to all stock numbers.

..... AVOID REPLACEMENT PART ERRORS...... File supplements and addendums immediately upon receipt, and consult the parts lists in them before ordering parts.

NOTE: For complete coverage of all parts and assembles used in inuments edulipped with the chassis series to which this service data relates, consist their clowing publications.

- Basic Service Data—Chassis and tuning systems and most related parts and assembles that do not differ from one model or model group to another
- Service Data Supplements—Cabinet, auxiliary, and other parts. and assemblies that differ from one model group to another
- Service Data Addendum—Any parts additions, deletions, or other changes made after initial production

Do not replace or order parts without first consulting any Addendum(s) that may have been issued since publication of this service

SYMBOL NO.	STOCK NO	DRAWING NO.	DESCRIPTION	SYMBOL NO	STOCK NO.	DRAWING NO.	DESCRIPTION	
UNDER:				R5308 R5917	160542 161710	2815583-747 2818520-48	RES CF 1/8W 2% 120K RES FUSE 1/2W 5% 22R	
ELECTRICAL COMPONENTS				U5101	155885	1421786-003	IC PLAYER CONTROL	
ADD:				UNDER:				
FL4101 FL4102 FL4103 FL4104	160168 160169 160170 160171	2861062-001 2861062-002 2861062-003 2861062-004	FILTER FILTER FILTER FILTER	MECHANICAL ASSEMBLY				
FL4105 FL4106	160172 160173	2861062-005 2861062-006	FILTER FILTER	CHANGE TO READ: 7	: 157845	2861019-002	BUTTON: POWER	
CHANGE TO READ								
J4602	157181	2816401-503	JACK AUDIO W/BRACKET					
Q6101	146847	1417306-013	TRANSISTOR ANTENNA BUFFER SWITCH					